

ENGINE LOG BOOK

	Total	Time	Time Sin Overl		Engine Service and Maintenance Re	ecor
Date	Hours	Min	Hours	Min	Record maintenance actions including engine part remoinstallation and compliance with inspections, Airworthiness D Special Inspections, Modifications and Service Bulletins	
ENGINE TSIO-55 ENGINE REG, NO WORK (0-K S/N: 1039109 D: N357JL DRDER:		gene ente	eral rpris	Repair Station No. NL.145.1305/GNSY577X/NL.MG.8305 Machlaan 6 9761TK Eelde The Netherlands Phone: +31 (0)50 3096060 DATE. 03 augustus, 2020 A/C TSN: 23.3 ENG TT: 23.2 TACH: 23.3	
l certify	that this eng	ine has bee ned Cylinder	n inspected i r - Flanged N	n accordan lut Corrosio	ce with 50 Hrs inspection and was determined to be in airworthy nand Prevention inspection i.a.w. CMI Standard Practice Manual M-0 Rev.	
——— Pertinent	details of the re	epair are on fi	le under Work	Order No. 11	3380-07-2020, Dated 03 augustus, 2020 at this Certified Repair Station # GNSY577X	
DATE:	03 augustus,	2020	SIGNED:		Work Order: 113380-07-2020	
			R. Drenth GE2 Certified Repai		NL.145.1305/GNSY577X/NL.MG.8305 Printed by EBis 3 (datcomedia.com)	
FOOT	58,8	<u>`</u>				
5 OET 1020						
TSIO-55 ENGINE REG. NO WORK (S/N: 1039109 D: N357JL DRDER:		gene	eral rprise	Repair Station No DATE: 03 augustus, 2020 NL. 145. 1305/GNSY577X/NL. MG.8305 A/C. TSN: 23.3 Machtlaan 6 ENG TT: 23.2 9761TK Eelde The Netherlands TACH: 23.3 Phone: +31 (0)50 3096060	
TSIO-55 ENGINE REG. NO WORK C 113380-I Engin	0-K S/N: 1039109 D: N357JL DRDER: 07-2020 HE Entries V that this eng		en inspected	in accordan	Repair Station No NL.145.1305/GNSY577X/NL.MG.8305 NL.145.1305/GNSY577X/NL.MG.8305 A/C TSN: 23.3 Machlaan 6 9761TK Eelde The Neitherlands Phone: +31 (0)50 3096060 ACH With Solution and Was determined to be in airworthy an and Prevention inspection i.a.w. CMI Standard Practice Manual M-0 Rev.	
TSIO-55 ENGINE REG. NO WORK C 113380-I Engin I certify conditio	0-K S/N: 1039109 D: N3567JL DRDER: 07-2020 ne Entries y that this engon Perfore	ned Cylinde	en inspected r - Flanged N	in accordan lut Corrosio	ce with 50 Hrs inspection and was determined to be in airworthy	
TSIO-55 ENGINE REG. NO WORK (113380-I Engin I certify conditio	0-K S/N: 1039109 D: N3567JL DRDER: 07-2020 ne Entries y that this engon Perfore	ned Cylinde	en inspected r - Flanged N	in accordan lut Corrosio	ce with 50 Hrs inspection and was determined to be in airworthy on and Prevention inspection i.a.w. CMI Standard Practice Manual M-0 Rev.	
TSIO-55 ENGINE REG. NO WORK (113380-1 Engin I certify conditio 0	0-K S/N: 1039109 D: N357JL DRDER: 07-2020 DE Entries y that this engon Perforn t details of the r	ned Cylinde	en inspected or - Flanged N file under Work SIGNED:	in accordant Corrosic	ice with 50 Hrs inspection and was determined to be in airworthy on and Prevention inspection i.a.w. CMI Standard Practice Manual M-0 Rev.	
TSIO-55 ENGINE REG. NO WORK (113380-1 Engin I certify conditio	0-K S/N: 1039109 D: N357JL DRDER: 07-2020 DE Entries y that this engon Perforn t details of the r	ned Cylinde	en inspected or - Flanged N file under Work SIGNED:	in accordant Corrosic	ice with 50 Hrs inspection and was determined to be in airworthy on and Prevention inspection i.a.w. CMI Standard Practice Manual M-0 Rev. 13380-07-2020, Daled 03 augustus, 2020 at this Certified Repair Station # GNSY577X Work Order: 113380-07-2020 Printed by EBis 3 (datcomedia.com)	
TSIO-55 ENGINE REG. NO WORK (113380-1 Engin I certify conditio	0-K S/N: 1039109 D: N357JL DRDER: 07-2020 DE Entries y that this engon Perforn t details of the r	ned Cylinde	en inspected or - Flanged N file under Work SIGNED:	in accordant Corrosic	ice with 50 Hrs inspection and was determined to be in airworthy on and Prevention inspection i.a.w. CMI Standard Practice Manual M-0 Rev. 13380-07-2020, Daled 03 augustus, 2020 at this Certified Repair Station # GNSY577X Work Order: 113380-07-2020 Printed by EBis 3 (datcomedia.com)	
TSIO-55 ENGINE REG. NO WORK (113380-1 Engin I certify conditio	0-K S/N: 1039109 D: N357JL DRDER: 07-2020 DE Entries y that this engon Perforn t details of the r	ned Cylinde	en inspected or - Flanged N file under Work SIGNED:	in accordant Corrosic	ice with 50 Hrs inspection and was determined to be in airworthy on and Prevention inspection i.a.w. CMI Standard Practice Manual M-0 Rev. 13380-07-2020, Daled 03 augustus, 2020 at this Certified Repair Station # GNSY577X Work Order: 113380-07-2020 Printed by EBis 3 (datcomedia.com)	
TSIO-55 ENGINE REG. NO WORK (113380-1 Engin I certify conditio	0-K S/N: 1039109 D: N357JL DRDER: 07-2020 DE Entries y that this engon Perforn t details of the r	ned Cylinde	en inspected or - Flanged N file under Work SIGNED:	in accordant Corrosic	ice with 50 Hrs inspection and was determined to be in airworthy on and Prevention inspection i.a.w. CMI Standard Practice Manual M-0 Rev. 13380-07-2020, Daled 03 augustus, 2020 at this Certified Repair Station # GNSY577X Work Order: 113380-07-2020 Printed by EBis 3 (datcomedia.com)	
TSIO-55 ENGINE REG. NO WORK (113380-1 Engin I certify conditio	0-K S/N: 1039109 D: N357JL DRDER: 07-2020 DE Entries y that this engon Perforn t details of the r	ned Cylinde	en inspected or - Flanged N file under Work SIGNED:	in accordant Corrosic	ice with 50 Hrs inspection and was determined to be in airworthy on and Prevention inspection i.a.w. CMI Standard Practice Manual M-0 Rev. 13380-07-2020, Daled 03 augustus, 2020 at this Certified Repair Station # GNSY577X Work Order: 113380-07-2020 Printed by EBis 3 (datcomedia.com)	
TSIO-55 ENGINE REG. NO WORK (113380-1 Engin I certify conditio	0-K S/N: 1039109 D: N357JL DRDER: 07-2020 DE Entries y that this engon Perforn t details of the r	ned Cylinde	en inspected or - Flanged N file under Work SIGNED:	in accordant Corrosic	ice with 50 Hrs inspection and was determined to be in airworthy on and Prevention inspection i.a.w. CMI Standard Practice Manual M-0 Rev. 13380-07-2020, Daled 03 augustus, 2020 at this Certified Repair Station # GNSY577X Work Order: 113380-07-2020 Printed by EBis 3 (datcomedia.com)	
TSIO-55 ENGINE REG. NO WORK (113380-1 Engin I certify conditio	0-K S/N: 1039109 D: N357JL DRDER: 07-2020 DE Entries y that this engon Perforn t details of the r	ned Cylinde	en inspected or - Flanged N file under Work SIGNED:	in accordant Corrosic	ice with 50 Hrs inspection and was determined to be in airworthy on and Prevention inspection i.a.w. CMI Standard Practice Manual M-0 Rev. 13380-07-2020, Daled 03 augustus, 2020 at this Certified Repair Station # GNSY577X Work Order: 113380-07-2020 Printed by EBis 3 (datcomedia.com)	

	Total	Time	Time Sir Over		Liigine oci vioo ana mame	
Date	Hours	Min	Hours	Min	Record maintenance actions including engine part removal installation and compliance with inspections, Airworthiness Directions and Inspections, Modifications and Service Bulletins	tives
rried forward						
NGINE MODEL: SIO-550-K2B NGINE SIN: 103910 SIO D-EUMK WORK ORDER: 14001-06-2021	9	gen	eral erpris	NL 14 Mach 9761	air Station No. DATE: 28 juli, 2021 ACTSN: 69 — IAS 1305/CNSY577X/NL.MG.8305 ENGTT, 58.7 hlaan 6 TACH: 69 TTK Eelde The Netherlands TACH: 69 ne +31 (0)50 3096060	
Engine Entries	•			1000 NO. NO.	LOAL 42772 Old rouising RB daire:	
1-9-2018 Perk njection System 652541) Inspecti 1 Performed E (P/N 646717) Se	rmed Fuel in Functional los in and Corres ingine Control vicing (P#: 6	pection i.a. sion Preven Linkage In: (46717) i.a.	w CMI Stand tion Inspection spection La.v w CMI Stand	dard Praction on (P#: 652 v CMI MM dard Practic	aintenance manual P/N:13773-001 revision B8 date: i.a.w CMI Standard Practice Manual M-0 Rev. 1 Performed Fuel ice Manual M-0 Rev. 1 Performed Cylinder - Flanged Nut (P/N) 2541) i.a.w CMI Standard Practice Manual M-0 Rev. TSIO550K M-18 Rev. 2 Performed Turbocharger Check Valve ice Manual M-0 Rev. 1	
General Enterprises certifies that the wor component is consic	B.V. Eelde NL.1 k specified exce ered ready for I	ept as otherwi release to ser	se specified wa vice	as carried out	t in accordance with PART-145 and in respect to that work the aircraft/ aircraft	
DATE: 28 juli, 20		SIGNED	6	£-39	Work Order: 114001-06-2021 Printed by EBis 3 (datcomedia.com)	
		Coramo			305/GINSY577X/INL MG 8305	
ENGINE MOD TSIO-550-K2I ENGINE S/N: REG. NO: D- WORK ORD 114962-09-21	3 1039109 EUMK ER:) 6	jener enterp	al orise:	Machlaan 6 DATE: 17 februari, 2023 ——————————————————————————————————	
TSIO-550-K2I ENGINE SO: REG. NO: D-I WORK ORDE 114962-09-21 Engine E I certify the condition M-0 Rev. 2 Cleaning S CMI Stand 2 Perfor	3 1039109 EUMK ER: 1022 Intries Intrie	has been in Cylinder - ! d Engine Ci . CMI Stand Manual M-Cope and too	Ispected in a Flanged Nut ontrol Linkag dard Practice O Rev. 2P k oil sample i	ccordance Inspection are Inspection with Manual Merformed Tillians and CMI are considered to the constant of t	Machlaan 6 9761TK Eelde The Netherlands Phone: +31 (0)50 3096060 With Annual inspection and was determined to be in airworthy and Corrosion Prevention Inspection i.a.w CMI Standard Practice Manual on CMI MM TSIO550K M-18 Rev. 0 Performed Fuel Injection Nozzles 10 Rev. 2 Performed Fuel Injection System Functional Inspection i.a.w. Turbocharger Check Valve i.a.w. CMI Standard Practice Manual M-0 Rev. Standard Practice Manual M-0 Rev. 2	
TSIO-550-K2I ENGINE 3R- REG. NO: D- WORK ORDE 114962-09-21 Engine E I certify the condition M-D Rev. 2 Cleaning S CMI Stand 2 Perfor General Entre certifies that component i	3 1039109 EUMK ER: 1022 Intries It this engine Performed Performed ard Practice rmed boresco	has been in Cytinder - ! d Engine C: . CMI Stan Manual M-C ope and too lide NL.145;13 fied except as ady for release	ispected in a Flanged Nut omtrol Linkag dard Practice O Rev. 2 P k oil sample is otherwise specie to service.	ccordance Inspection are Inspection with Manual Merformed Tillians and CMI are considered to the constant of t	Machlaan 6 9761TK Eelde The Netherlands Phone: +31 (0)50 3096060 With Annual inspection and was determined to be in airworthy and Corrosion Prevention Inspection i.a.w CMI Standard Practice Manual on CMI MM TSIO550K M-18 Rev. 0] Performed Fuel Injection Nozzles On CMI Rev. 2] Performed Fuel Injection System Functional Inspection i.a.w.	
TSIO-550-K2I ENGINE 3R- REG. NO: D- WORK ORDE 114962-09-21 Engine E I certify the condition M-D Rev. 2 Cleaning S CMI Stand 2 Perfor General Entre certifies that component i	3 1039109 EUMK IR: 1022 Intries It this engine PerformedPerformed and Practice Tred boresco	has been in Cytinder - I d Engine C. CMI Stan Manual M-C ope and too olde NL.145:13 Fied except as ady for release	ispected in a Flanged Nut ordrol Linkag dard Practice D Rev. 2. J Pk oil sample is offeniss Special Control of the Nut	ccordance inspection a e Inspection e Manual erformed Ti i.a.w. CMI	Machiana 6 9761TK Eelde The Netherlands Phone: +31 (0)50 3096060 with Annual inspection and was determined to be in airworthy and Corrosion Prevention Inspection i.a.w CMi Standard Practice Manual on CMi MM TSIO550K M-18 Rev. 0	
TSIO-550-K2I ENGINE 30: D-I WORK ORDE 114962-09-21 Engine E I certify the condition M-0 Rev. 2 Cleaning S CMI Stand 2 Perfor General Entre certifies that component i	3 1039109 EUMK ER: 1022 Intries It this engine Performed Performed ard Practice rmed boresco	has been in Cytinder - I d Engine C. CMI Stan Manual M-C ope and too olde NL.145:13 Fied except as ady for release	ispected in a Flanged Nut ordirol Linkag dard Practice I Rev. 2 I. Pk to il sample i officerise specie to service IGNED:	ccordance inspection a e Inspection e Manual erformed Ti i.a.w. CMI	Machiana 6 9761TK Eelde The Netherlands Phone: +31 (0)50 3096060 with Annual inspection and was determined to be in airworthy and Corrosion Prevention Inspection i.a.w CMi Standard Practice Manual on CMi MM TSIO550K M-18 Rev. 0	
TSIO-550-K2I ENGINE 30: D-I WORK ORDE 114962-09-21 Engine E I certify the condition M-0 Rev. 2 Cleaning S CMI Stand 2 Perfor General Entre certifies that component i	3 1039109 EUMK ER: 1022 Intries It this engine Performed Performed ard Practice rmed boresco	has been in Cytinder - I d Engine C. CMI Stan Manual M-C ope and too olde NL.145:13 Fied except as ady for release 3	ispected in a Flanged Nut ordirol Linkag dard Practice I Rev. 2 I. Pk to il sample i officerise specie to service IGNED:	ccordance inspection a e Inspection e Manual erformed Ti i.a.w. CMI	Machiana 6 9761TK Eelde The Netherlands Phone: +31 (0)50 3096060 with Annual inspection and was determined to be in airworthy and Corrosion Prevention Inspection i.a.w CMi Standard Practice Manual on CMi MM TSIO550K M-18 Rev. 0	
TSIO-550-K2I ENGINE 30: D-I WORK ORDE 114962-09-21 Engine E I certify the condition M-D Rev. 2 Cleaning S CMI Stand 2 Perfor General Entre certifies that component i	3 1039109 EUMK ER: 1022 Intries It this engine Performed Performed ard Practice rmed boresco	has been in Cytinder - I d Engine C. CMI Stan Manual M-C ope and too olde NL.145:13 Fied except as ady for release 3	ispected in a Flanged Nut ordirol Linkag dard Practice I Rev. 2 I. Pk to il sample i officerise specie to service IGNED:	ccordance inspection a e Inspection e Manual erformed Ti i.a.w. CMI	Machiana 6 9761TK Eelde The Netherlands Phone: +31 (0)50 3096060 with Annual inspection and was determined to be in airworthy and Corrosion Prevention Inspection i.a.w CMi Standard Practice Manual on CMi MM TSIO550K M-18 Rev. 0	
TSIO-550-K2I ENGINE 30: D-I WORK ORDE 114962-09-21 Engine E I certify the condition M-D Rev. 2 Cleaning S CMI Stand 2 Perfor General Entre certifies that component i	3 1039109 EUMK ER: 1022 Intries It this engine Performed Performed ard Practice rmed boresco	has been in Cytinder - I d Engine C. CMI Stan Manual M-C ope and too olde NL.145:13 Fied except as ady for release 3	ispected in a Flanged Nut ordirol Linkag dard Practice I Rev. 2 I. Pk to il sample i officerise specie to service IGNED:	ccordance inspection a e Inspection e Manual erformed Ti i.a.w. CMI	Machiana 6 9761TK Eelde The Netherlands Phone: +31 (0)50 3096060 with Annual inspection and was determined to be in airworthy and Corrosion Prevention Inspection i.a.w CMi Standard Practice Manual on CMi MM TSIO550K M-18 Rev. 0	
TSIO-550-K2 ENGINE 30: D- WORK ORDE 114962-09-21 Engine E I certify the condition M-D Rev. 2 Cleaning S CMI Stand 2 . Perfor	3 1039109 EUMK ER: 1022 Intries It this engine Performed Performed ard Practice rmed boresco	has been in Cytinder - I d Engine C. CMI Stan Manual M-C ope and too olde NL.145:13 Fied except as ady for release 3	ispected in a Flanged Nut ordirol Linkag dard Practice I Rev. 2 I. Pk to il sample i officerise specie to service IGNED:	ccordance inspection a e Inspection e Manual erformed Ti i.a.w. CMI	Machiana 6 9761TK Eelde The Netherlands Phone: +31 (0)50 3096060 with Annual inspection and was determined to be in airworthy and Corrosion Prevention Inspection i.a.w CMi Standard Practice Manual on CMi MM TSIO550K M-18 Rev. 0	
TSIO-550-K2 ENGINE 30-P WORK ORDE 114962-09-21 Engine E I certify the condition M-0 Rev. 2 Cleaning S CMI Stand 2 Perfor	3 1039109 EUMK ER: 1022 Intries It this engine Performed Performed ard Practice rmed boresco	has been in Cytinder - I d Engine C. CMI Stan Manual M-C ope and too olde NL.145:13 Fied except as ady for release 3	ispected in a Flanged Nut ordirol Linkag dard Practice I Rev. 2 I. Pk to il sample i officerise specie to service IGNED:	ccordance inspection a e Inspection e Manual erformed Ti i.a.w. CMI	Machiana 6 9761TK Eelde The Netherlands Phone: +31 (0)50 3096060 with Annual inspection and was determined to be in airworthy and Corrosion Prevention Inspection i.a.w CMi Standard Practice Manual on CMi MM TSIO550K M-18 Rev. 0	
TSIO-550-K2 ENGINE 20: D- WORK ORDE 114962-09-21 Engine E I certify the condition M-0 Rev. 2 Cleaning S CMI Stand 2 Perfor	3 1039109 EUMK ER: 1022 Intries It this engine Performed Performed ard Practice rmed boresco	has been in Cytinder - I d Engine C. CMI Stan Manual M-C ope and too olde NL.145:13 Fied except as ady for release 3	ispected in a Flanged Nut ordirol Linkag dard Practice I Rev. 2 I. Pk to il sample i officerise specie to service IGNED:	ccordance inspection a e Inspection e Manual erformed Ti i.a.w. CMI	Machiana 6 9761TK Eelde The Netherlands Phone: +31 (0)50 3096060 with Annual inspection and was determined to be in airworthy and Corrosion Prevention Inspection i.a.w CMi Standard Practice Manual on CMi MM TSIO550K M-18 Rev. 0	

	Total Time Hours Min		Time Since Last Overhaul Hours Min		Record maintenance actions including engine part removal and installation and compliance with inspections, Airworthiness Directives,				
Date									
					Special Inspections, Modifications and Ser	vice Bulletins			
ried forwa						100			
	ENGINE MODE TSIO-550-K2B		€ ge	ner	Machlaan 6 9761TK Eelde The Netherlands	DATE: 24 april, 2024 A/C TSN: 75			
	ENGINE S/N: 10 REG. NO: D-EU WORK ORDER 115799-11-2023	MK :	general Machlaan 6 9761TK Eelde The Netherlands enterprises Machlaan 6 9761TK Eelde The Netherlands Phone: +31 (0)50 3096060 DATE: 24 april, 2024 AVC TSN: 75 ENG TT: 74.9 TACH: 75						
	Engine En	tries							
	9-11-2021	Performed ual M-0 Re Nozzles C spection i.a Rev. 4 P d cvl #6 as	d Cylinder - Fla v. 4 Perform leaning Servicii .w. CMI Standi erformed Turbo sv (OutP#:658)	nged Nut ned Engin ng , iaw (ard Pract ocharger 815A1 St	Cirrus Design Maintenance manual P/N:13773-002 revie (P/N 652541) Inspection and Corrosion Prevention Inspection i.a.w. CMI MM TSIO550K II Control Linkage Inspection i.a.w. CMI MM TSIO550K II SMI Standard Practice Manual M-0 Rev. 4 Performed ice Manual M-0 Rev. 4 Performed Oils anual M-0 Rev. 4 Performed ice Manual M-0 Rev. 4 .	ection i.a.w. CMI Standard January Standard January CMI Standard January CMI Standard Practice January CMI Standard Practice Practice Manual M-0 Rev. Continental M-0, chapter			
			Ide NL.145 1305						
			ied except as othe ady for release to		ified was carried out in accordance with PART-145 and in respect	to that work the aircraft/ aircraft			
	DATE: 24 ap	ril, 2024	SIGNI	ED:	V	Vork Order: 115799-11-2023			
			S. Van	t Zand, Lic	Printed	by EBis 3 (datcomedia.com)			
				4000					
						8			
40000000				and the second		¥			
						<u>*</u>			
				ilioticate all comments					
					41				
200					,	•			